1/7





FIG. 1



13

3/7
23
26
29
27
30
41
41
42




FIG. 5




FIG. 6






FIG. 7






14

VIBRATOR MOTOR
Brill et al.
Greer, Burns & Crain, Ltd. (Patrick Burns)
Ref. No. 2206.64630
Sheet 7 of 7 (312) 360 0080

7/7



Hall the same own on the same of the same F. C. F. Sunt. F. Sunt. Bull.